

# AEECoW

The Association of Environmental & Ecological Clerks of Works

## Case Study

<b>Project Name</b>	<b>Sconser Ferry Terminal</b>
<b>Project Details</b>	Upgraded terminal and extension to slipway to accommodate larger vessel
<b>Location</b>	Sconser, Isle of Skye
<b>ECoW</b>	EnviroCentre Ltd
<b>Sensitive Ecological/ Environmental Features</b>	<ul style="list-style-type: none"><li>• Loch Sligachan</li><li>• Marine mammals</li><li>• Horse mussel beds</li><li>• Wig wrack</li><li>• Otter</li></ul>
<b>ECoW Context</b>	To provide supervision based on the Environmental Management Plan
<b>ECoW Role</b>	<ul style="list-style-type: none"><li>• To report to the contractor and support their existing environmental management procedures</li></ul>
<b>Site Photographs</b>	